





Figure 4
REHABILITATION PLAN

-  3:1 REHABILITATION SLOPE, 1m CONTOURS
-  NATURAL ENVIRONMENT SLOPE TREATMENT

Scale: 1:6,000



Cambridge Aggregates Inc. / Italcementi Group, December 2009
 Natural Environment Level 1 and 2 Technical Report
 GOODBAN ECOLOGICAL CONSULTING INC.